


## EXTREME DUTY CRUSHER MOTOR




Crusher Motor Fan End



Crusher Motor Shaft End




The V Seal Slinger  
Mounted on the Shaft




The V Seal Shown Mounted in the Bearing  
Cap



SKF NU324EC Bearing on Shaft End




VPI and Fully Rapped End Turns



A large Terminal Block is provided for easy hook up. The Terminal block can be removed and the twelve leads can be configured for a Part Wind or Wye Delta Soft Start Application

A Separate Terminal Block is also provided to Connect the Heater and Thermister



Cast Iron Conduit Box



Separate Wiring Diagrams, One for Power and One for the Heater and Thermistors